


# Fuel Oil non-availibilty report

Name of Vessel:	<i>"LINDA Oldendorff"</i>	Flag:	<i>Madeira</i>	IMO Number:	9691929
(if other relevant registration # enter here) :					
Provide a description of the vessel's voyage plan in place at the time of entry into the North American ECA (Attach copy of plan if available) :					
49-28.2N 134-46.0W; 48-28-55N 125-09.0W; 48-28.5N 125-00.0W ;48-28.5N 124-43.8W; 48-13.4N 123-54.8W; 48-13.4N 123-40.0W; 48-15.5N 123-26.5W; 48-21.9N 123-23.1W					
Port of Origin:	Yeosu	Date:	17.11.2014		
Port of Destination:	Roberts Banks /Canada	First US port of Arrival:	N/A		
Date vessel first received notice that it would be transiting in the N. American ECA:					12.11.2014
Vessel's location at the time of notice:		Tianjin Xingang /China			
Date/Time ship operator expects to enter N American ECA:			2811.2014 AM		
Date/Time ship operator expects to exit N American ECA:			10.12.2014 AM		
Projected days ship's main propulsion engines will be in operation within N American ECA:					Abt.6-8 days
Sulfur content of fuel oil in use when entering and operating in the N American ECA:					3,0%
Provide a description of actions taken to attempt to achieve compliance prior to entering North American ECA, including a description of all attempts that were made to locate alternative sources of compliant fuel oil, and a description of the reason why compliant fuel oil was not available:					

[illegible]

	If Applicable
Describe any operation constraints that prevented using available compliant fuel oil (e.g. with respect to viscosity or other fuel oil parameters):	N/A
Specify steps you have taken, or are taking, to resolve these operational constraints that will allow you to use all commercially available residual fuel oil blends:	N/A

Describe availability of compliant fuel oil at the first port-of-call in the United States, and plans to obtain that fuel oil:							
If compliant fuel oil is (was) not available at the first port-of-call in the United States, list the lowest sulfur content of available fuel oil(s) or the lowest sulfur content of available fuel oil at the next port-of-call in the United States:							
List below U.S. ports visited in the last 12 months:			If vessel or owner/operator has submitted a Fuel Oil Non-Availability Report to the United States Government in the previous 12 months, list the number of Fuel Oil Non-Availability Reports previously submitted and provide details on the dates and ports visited while using non-compliant fuel oil:				
Name	Date	Did vessel use compliant fuel oil? (yes/no)					
a)			Report	Date	Port	Type of Fuel	Comments
b)			1)				
c)			2)				
d)			3)				
e)			4)				
Ship Master Name:		Captain Verbin Anatoliy		Ship Operator Name:		Oldendorff Carriers GmbH & Co. KG.	
Legal Agent in the U.S.:		N/A		Ship Owner Name:		Oldendorff Carriers GmbH & Co. KG.	
Name of designated Corporate Official:							
Address (Street, City, Country, Postal Code):			WILLY-BRANDT-ALLEE 6 D-23554 LÜBECK GERMANY MAILING ADDRESS P.O. BOX 21 35 D-23509 LÜBECK GERMANY				

I hereby certify under penalty of law that the statements and information made herein are, to the best of my knowledge and belief, true and complete. I am aware that there are significant penalties for knowingly submitting false statements and information, including possibility of fines and imprisonment pursuant to 18 U.S.C. 1001		
Signature 	Print Name Captain Verbin Anatoliy	Date 20.11.2014

**LINDA OLDENDORFF**  
 Buchanan Maritime Corporation